



U.S. Department
of Transportation
**Federal Aviation
Administration**

Federal Aviation Administration
FAASTeam
1102 Corporate Way
Bldg. B, Suite 200
Sacramento, CA 95831

December 15, 2010

Mike James
Operations Manager
AMETEK B&S Aircraft Parts & Accessories
1414 South Mosley
Wichita, Kansas 67211-3387
316-264-2397
<Mike.James@ametek.com>

Dear Mr. James:

The Federal Aviation Administration (FAA) is pleased to notify you that we have accepted the 1-hour course titled, "Turbocharged Engine Systems" that you submitted for Inspection Authorization (IA) refresher training.

As of this date, the material submitted meets the requirements of Title 14 of the Code of Federal Regulations (14 CFR) part 65, § 65.93(a) (4), for IA renewal.

Your new assigned program identification number is: C-IND-IM-101215-K-006-01.

Your course will remain on the FAA's active list of accepted IA renewal courses for 24 calendar-months unless suspended or removed for cause.

Before the end of the 24 calendar-month period, you must provide the IA Refresher Course Coordinator (IA RCC) with a request for course renewal acceptance in accordance with current guidelines. If you do not provide this request at least 60 days before the end of the 24-month period, we will remove your course from the list of acceptable courses.

As a provider of an FAA-accepted IA training course, you must comply with current guidance to remain valid.

Your course is subject to FAA review. If the reviewing FAA Aviation Safety Inspector determines that your course does not meet the guidelines, you will receive notification.

Your FAA-accepted course number, C-IND-IM-101215-K-006-01, will expire December 31, 2012.

Congratulations, and thank you for your interest in aviation safety. Should you have further questions, please contact me at (916) 422-0272 Ext. 254

Sincerely,

A handwritten signature in blue ink, appearing to read 'DR Green', with a stylized flourish at the end.

Donald R. Green
FAASTeam
IA Refresher course coordinator